


TILTED COLUMN CP



d1	L	b	ITEM CODE
12	50	4	CP12050
12	75	4	CP12075
12	100	4	CP12100
12	125	4	CP12125

d1	L	b	ITEM CODE
25	125	6	CP20125
25	150	6	CP20150
25	175	6	CP20175
25	200	6	CP20200

d1	L	b	ITEM CODE
16	75	6	CP12075
16	100	6	CP12100
16	125	6	CP12125
16	150	6	CP12150

d1	L	b	ITEM CODE
30	150	8	CP30150
30	175	8	CP20175
30	200	8	CP20200
30	250	8	CP20250

d1	L	b	ITEM CODE
20	100	6	CP20100
20	125	6	CP20125
20	150	6	CP20150
20	175	6	CP20175

Mat : 1.7131 ≈ 58-60 HRc.

INCLINED ASSEMBLY CI

$\alpha = 7^\circ / 10^\circ / 12^\circ / 15^\circ / 18^\circ / 20^\circ / 22^\circ$



The position of the screws
determines the mounting position.

